

PATTON ELECTRONICS

Patton Electronics Company MATA Release Note SIP version 4.02.0A1 MS VR CS (0011)

Bug Fixes:

1. Fixed T.38 issue where device cannot train successfully under 14400 bps.
2. Append telephone-event number in SDP codec list.
3. Append T.38 TranscodingMMR, version and MaxDatagram attribute in SDP.
4. Fixed double "a=rtpmap:96 telephone-event/8000" in SDP.
5. Disable caller reinvite to T38 when detect FAX tone.

Added Features:

1. Changed loop current from 20mA to 38mA.
2. Configurable option for Battery Reversal on the FXS port has been added and configurable without a reboot.
3. Add auto reload web page after config update.
4. Add config backup and update function.
5. Added a 5 min check server FQDN task. If IP changes, it will register to the new one.