



Patton Electronics Company, Inc.

7622 Rickenbacker Drive

Gaithersburg, MD 20879 USA

Tel. +1 (301) 975-1000

Fax +1 (301) 869-9293

support@patton.com

<http://www.patton.com>

Customer Deliverable Documentation
Revision 1.00, September 14th, 2017.

SmartMedia v2.8.132 Release Notes

New to the v2.8.132 Release

Bug Fixes:

- SIP: Several memory corruptions fixes from 3.0.

Enhancements:

- Possible to Modify SIP User-Agent and Server headers

History of Solved CTS Cases

The following list refers to open cases in the Change Tracking System 'CTS'

Build Series v2.8.131

Bug Fixes:

- The M bit is set to 1 for non-ported number with Outgoing Calls LNP Mode: Relay
- Fax are not passing in pass-through when FAX tone detection is enabled on the IP side of IP<->TDM call
- Redirecting and original called number removed in SIP-I
- ACM/CPG diversion parameter mapping from ISUP/ISDN to SIP

Build Series v2.8.130

Bug Fixes:

- From tag was changed after 401 authorization
- Add Redirect Information in SS7 REL message
- Watchdog could resets telecom unit due to slow access in refresh ISR
- Increase Route: Called and Calling field to support up to 2000 chars
- Enable SIP quirk to add brackets in SIP URIs in headers: From, To, Contact

Enhancements:

- Support up to than 1024 NAPs

Build Series v2.8.129

Bug Fixes:

- Too many IP interfaces with SIGTRAN service

- Support to add IP address in INIT_ACK

WWW

Please refer to the following online resources:

- Software Configuration Guide SmartMedia:
<http://www.patton.com/manuals/SmartMedia-scg.pdf>
- SmartMedia Configuration Library:
<http://www.patton.com/support/kb.asp?cat=114>
- SmartMedia FAQ:
<http://www.patton.com/support/kb.asp?cat=75>

How to Upgrade

Please see http://www.patton.com/support/kb_art.asp?art=326.