Technote # 100025	Model 1092 & 1092A: System Clock Mode Configuration	Date April 28, 1999

Revised description of clocking configuration.
Replace the boxed description on page 8 of the 1092A manual and
page 7 of the 1092 Manual.
Important: Since the Model 1092A BaseBand Modems use the
2B1Q modulation/encoding scheme of transmission on the twisted
pair line, the configuration of the clock mode for each modem is
critical.
Please configure **one Model 1092A for Receive Recover clock
mode** and **the other 1092A for either a) Internal or
b) External (DTE).**
This applies for both asynchronous or synchronous operation.

 100025|^Model 1092 & 1092A: System Clock Mode Configuration|^April 28, 1999|^

|^Submit New Technote|^

PATTON ELECTRONICS CO. TECHNICAL SUPPORT