

What's new in release 2.6.84

=====

- Issue fixes:

- ISUP and VC4 Line service status page refresh failed (Server is not responding)
- Invalid congestion in sip stack
- Increase the maximum number of SIP Service Access Points (SAPs)
- Race condition in CTBCAFTimer causing issue in TBOamApp during background installation
- Failed to convert BITS port name to user contexts!
- H.248 Line Service OutOfService when Code violations are detected.
- Can't set CDR max size on disks to something larger than 2GB
- SIP Q.850 reason in message header
- SIP TS server could not be deleted (incorrectly reported as "still in use")