



Patton Electronics Company, Inc.

7622 Rickenbacker Drive

Gaithersburg, MD 20879 USA

Tel. +1 (301) 975-1000

Fax +1 (301) 869-9293

support@patton.com

<http://www.patton.com>

SmartMedia v2.9.72 Release Notes

New to the v2.9.72 Release

Bug Fixes:

- Specific SIP call flow is leaking internal buffer making NAP to become unavailable

WWW

Please refer to the following online resources:

- Software Configuration Guide SmartMedia:
<http://www.patton.com/manuals/SmartMedia-scg.pdf>
- SmartMedia Configuration Library:
<http://www.patton.com/support/kb.asp?cat=114>
- SmartMedia FAQ:
<http://www.patton.com/support/kb.asp?cat=75>

How to Upgrade

Please see http://www.patton.com/support/kb_art.asp?art=326.